

## Kyoritsu 1110 Multi Meter

### Features at a glance

- High sensitivity DC20kΩ/V.
- 1m drop-proof heavy duty design.
- Can measure line voltage up to AC 600V. (Voltage to ground MAX AC 300V)
- (Protected by 600V ceramic fuse against accidental overload)
- Continuity buzzer, battery check, LED check function.
- Skeleton type robust and clear case with carrying handle furnished as standard accessory

## **Specifications**

| DC V                 | $0.3V(16.7k\Omega/V) \pm 3\%$ of FS $3/12/30/120/300/600V(20k\Omega/V) \pm 3\%$ of FS   |
|----------------------|---|
| AC V                 | 12V(9k $\Omega$ /V) ±4% of FS 30/120/300/600V(9k $\Omega$ /V) ±3% of FS   |
| DC A                 | 60μA/30/300mA ±3% of FS   |
| Ω                    | $3/30/300$ k $\Omega$ $\pm 3\%$ of scale length   |
| Continuity buzzer    | Buzzer sounds below $100\Omega$   |
| Battery Test         | 1.5V(0.7 - 2V) ±3% of FS (10Ω load)   |
| LED                  | 10mA approx. at $0\Omega$ (at 3V of battery voltage)  |
| Applicable Standards | IEC 61010-1 CAT III 300V /CATIII 600V, IEC 61326-1  |
| Power source         | R6(AA)(1.5V) × 2  |
| Dimensions           | 140(L) × 94(W) × 39(D)mm  |
| Weight               | 280g approx.  |
| Accessories          | 7066A (Test leads), 8923 Fuse [500mA/600V]) $\times$ 2,R6(AA) $\times$ 2, 9103( Carrying case), Instruction manual8923 (Fuse[500mA/600V]) $\times$ 2,R6(AA) $\times$ 2, 9103(Carrying case), Instruction manual |
|                      |   |



## Specifications

| DC V         | $0.1/0.5/2.5/10/50/250/1000V(20k\Omega/V)$ ±3% of FS                                      |
|--------------|---|
| AC V         | $10/50/250/1000V(9k\Omega/V) \pm 3\%$ of FS   |
| DC A         | 50μA/2.5/25/250mA ±3% of FS   |
| Ω            | $2/20k\Omega/2/20M\Omega$ ±3% of scale length   |
| Decibel      | -10 - +62dB   |
| hFE          | 0 - 1000(Ω × 10) ±3% of scale length  |
| Power source | R6(AA)(1.5V) × 2, 6F22(9V) × 1  |
| Dimensions   | 150(L) × 100(W) × 47(D)mm   |
| Weight       | 330g approx   |
| Accessories  | 7066A(Test leads), 8901(Fuse[0.5A/250V]) × 2,<br>R6(AA) × 2, 6F22 × 1, Instruction manual |
| Optional     | 9168(Carrying case)   |

# Kyoritsu 1109S Multi Meter

#### Features at a glance

- Mirrored scale for easy and accuratereading.
- Output terminal to cut off DC component when measuring AC voltage.
- Safety designed input terminals and test leads.